3012705

WEEKLY TANK INSPECTION REPORT

K # OK	HEEDS PEPAIR	TANK #	οк	MEEDS REPAIR	
<u> </u>	The same of the sa	105	V	Britispedin water the Artisped Artispeding	
	demonstrative destinants a contra con contrativa de representando aldo contrativa alta alteria contra de electrida con indicado con contrativa de contrativa con contrativa de contrativa contrati	106	V	terminated anaport to the color of the anapolic and a single	Con
-	the contraction of the contracti	107	1	Company and the contract of the party of the contract of the c	***************************************
		108	_	Control of the contro	
~		109	1	of effects and residence of the second of th	
	destination to add the add to the advertise and the street to a destination of the destination of the destination of the advertise and the	110	1		
V		11.1	1		
V	Section Selection of the Association of the Associa	112	_		
1	Endlighte Stantille des vitas di vitas de vitas anno la des consentates anno de de de la consentate de la co	113	er-silven ,		
_	Antitional front in the state of the state o	114	_		
,	Continue to the distribution of the continue o	115	_		
1		116	/		
?		117	/		
3		118	2		
		165	White wa		
SEL YAR yard b	yard berms OK NEEDS REPAIR_ D berms OK NEEDS REPAIR_ erms OK NEEDS REPAIR COMMENTS RAN FERM DUMPS EAK REPAIRED 4-15-86		2		
A nional Anional Aniona A					
Reported_	bosmoody	1986			USEPA RCF